

ALT-8000 Radio Altimeter, Part Number 87340; New Release of ALT-8000 Software Version 1.4.1 and Operations Manual

This information bulletin is to inform current users of the ALT-8000 of a new version of operational software and operations manual that is currently available for download.

Effectivity:

Available for all ALT-8000 test set users who want to install this operational software update. Implementation of this version of software will change the currently installed version to 1.4.1. The updated ALT-8000 operations manual will detail some of the touchscreen changes caused by the new software.

Summary of changes:

1. Product improvement: Adds support of the GRA55 altimeter which requires RF firmware v1.04.00 or higher. If the ALT-8000 RF module has a lower version, unit will show message stating RF firmware needs updating to support GRA55.

NOTE: This RF firmware update is a factory only update. Contact Techsupport.Avcomm@viavisolutions.com or visit our website to request an RMA at <https://portal.viavisolutions.com/request-rma>

2. Product improvement: Added indications when UUT measurements are stale – measurement readings will go grey.
3. Product improvement: Delay calibration screen now returns to the calibration screen so results can be seen immediately and a popup bubble will appear stating if calibration was completed successfully or not.
4. Product improvement: Adds a self-test routine to help user verify if the ALT-8000 is functioning properly or not.

Note: Installation of F/W upgrade adds self-test capability to the menu selection. With some



- ## Downloading and Installing New Software: